

## 2004 Ford F-350 SUPER DUTY PICKUP

Submodel: | Engine Type: V8 | Liters: 6.0

Fuel Delivery: FI | Fuel: DIESEL

---

### DTC Code P2703

---

**DTC Code:**

P2703

Description: Transmission Friction Element ?D? Apply Time Range / Performance

**Probable Causes:**

1. Sensor or solenoid faulty
2. Connector terminal contact is damaged or corroded
3. Wire harness - Check harness for correct voltage, open, short to ground or short to voltage
4. Update control unit software - Check for the latest control unit update
5. Powertrain or Engine Control Module faulty
6. Transmission system malfunction